

RECEIVING INSPECTION REPORT  
HYCON MFG. COMPANY

No. 12193

Approved For Release 2000/04/18 : CIA-RDP81B00879R000500080077-9

RECEIVED FROM

DATE REC'D 5-16-57

P.O. NO.

VENDOR PACKING SLIP NO.

Plant #9

CONTRACT CODE NO.	DRAWING NUMBER	DWG. DASH OR STANDARD PART NO.	DWG. REV.	LOT NO.	CLASS NUMBER	OPER. NUMBER	BUY OUT CODE NO.	ACCT. OR W.O. NO.	S.O. NO.
322	000000	005	0	10					

CHANGE TO QUANTITY RECEIVED	DRAWING NO. AND DESCRIPTION	QUANTITY		REMARKS
		ACCEPTED	REJECTED	
1	731983 Pin T.C. 11  I.P. 7684	1		Full Store  M.E. Kender

RECEIVED BY *Barcellos*  
HMC-1005

INSPECTED BY *JPE*

DATE 5-16-57

REJECTS RETURNED ON SHIP. MEMO NO.

RECEIVING INSPECTION REPORT  
HYCON MFG. COMPANY  
2961 E. COLORADO ST., PASADENA, CALIF.

No. 12195

RECEIVED FROM

DATE REC'D 5-16-57

P.O. NO.

VENDOR PACKING SLIP NO.

Plant #

CONTRACT CODE NO.	DRAWING NUMBER	DWG. DASH OR STANDARD PART NO.	DWG. REV.	LOT NO.	CLASS NUMBER	OPER. NUMBER	BUY OUT CODE NO.	ACCT. OR W.O. NO.	S.O. NO.
322	000000	026	0	10					

CHANGE TO QUANTITY RECEIVED	DRAWING NO. AND DESCRIPTION	QUANTITY		REMARKS
		ACCEPTED	REJECTED	
15	737118 Washer Retainer Pivot  I.P. 7682	15		Full Store  M.E. Kender

RECEIVED BY *Barcellos*  
HMC-1005

INSPECTED BY *JPE*

DATE 5-16-57

REJECTS RETURNED ON SHIP. MEMO NO.

Approved For Release 2000/04/18 : CIA-RDP81B00879R000500080077-9